# EDVIR PROCESS DRIVER PROCESS

ALL DEFECTS IN NEED OF REPAIR SHOULD BE REPORTED PHYSICALLY TO THE REPAIRING SHOP. PLEASE, REPORT THE LOCATION OF THE VEHICLE AND THE REPAIR REQUIRED. PLEASE, BE CLEAR IN YOUR DESCRIPTION OF ALL DEFECTS. THE FOLLOWING PAGES ARE A GUIDE TO USING EDVIR ON YOUR GEOTAB APPLICATION.

JACK COOPER TRANSPRT AND NORTH AMERICAN TRANSPORT

## **DVIR INSPECTION AND REPAIR CERTIFICATION**

JCTtest1 (JCT123)

TEST

r d f

z x

TESTING 2 3 4 5 6 7 8 9 0 Del

t y u i

g h j

c v b n m

English (US)

NI O 10 1 275 E ×

TESTS TEST

k 1 Go

о р 🛥

,1 .? 🕈

4

STEP 1 – GETTING CONNECTED TO THE TRUCK

- 1. SELECT VEHICLE
- 2. ONCE DEVICE IS SELECTED SAVE AND CONTINUE
- 3. CHOOSE NO VEHICLE IF YOU DO NOT WANT TO GO ON DUTY

Select Vehicle		×	Select V
Find vehicles		Ø	Find ve
Name, VIN, or	serial number		TEST
Could h	ot find any recent or nearby v	ehicles.	JC1
			(5)
			1 2
			q w
			а
_			<b>†</b> z
	No vehicle		Ctrl #
8.03 <b>- 2</b> G # X	- a	<b>4) 0</b> %, a) 29%, â	
8.03 ∎≢ Gar X Assets	4-9	*i o 15.41 29% 분 *	
too ∎≢carr× Assets Southicle		×[ 0 %	
eos∎∉G≖× Assets ∎ Vehicle JCTtest1		x10 %;u) 295;4 ×	
ect E = c = X Assets D Vehicle JCTtest1 Trailers		×10 % 2 29% 4 ×	
Assets Vehicle JCTtest1 Trailers	No trailers attached	NI 9 %.4 2014 X O	
Assets b Vehicle JCTtest1 Trailers	No trailers attached	NI 9 % // 2016.8 X •	
Assets Note: Shipments	No trailers attached	NI 9 75.4 2015.8 ×	
Assets D Vehicle JCTtest1 Trailers Shipments	No trailers attached	NI 0 %.4 2015.8 × •	
Assets Vehicle JCTtest1 Trailers Shipments	No shipments attached	NI 975-2 2954 ×	
Assets  Vehicle JCTtest1  Trailers  Shipments	No trailers attached No shipments attached	NI 9 % J 2014 X •	
Assets  Vehicle JCTtest1  Trailers  Shipments	No trailers attached No shipments attached	NI 9 % J 2015.8 ×	
Assets Assets Vehicle JCTtest1 Trailers Shipments	No trailers attached No shipments attached	× × ×	
Assets Vehicle JCTtest1 Trailers Shipments	No trailers attached	NI 0 %.4 2015.8 ×	

STEP 2 - SEPERATING FROM THE TRUCK WHEN ANOTHER MAY NEED TO DRIVE THE TRUCK (SHOP)

- 1. ON THE DASHBOARD FIND THE TRUCK SYMBOL. WHEN A TRUCK IS LISTED, YOU ARE CONNECTED TO THAT TRUCK. CLICK ON THE TRUCK NUMBER
- 2. ON THE NEXT ASSET PAGE CLICK THE BLACK DOT WITH AN X
- 3. YOU ARE NOW SEPERATED FROM THE TRUCK



<ul> <li>Assets</li> </ul>		1		1 ?
	Your ELD ha	is diagnostics. Te	ap for details.	
Sehicle				
JCTtest1				ø
Trailers				•
	No	trailers attac	ched	
Shipments				•
	No sł	hipments att	ached	
		0		



STEP 3 – THE DVIR INSPECTION PROCESS

- 1. CHOOSE INSPECT
- 2. MAKE SURE YOU'RE USING THE DEFAULT INSPECTION BY TRAILER OR VEHICLE AND NOT "CTPAT" THAT IS FOR BORDER CROSSING ONLY"
- 3. YOU ALSO MUST CHECK THE NO DEFECTS FOR YOUR HEIGHT. THIS WILL VERY YOU ARE 13'6" OR LESS
- 4. IF NO DEFECTS ARE FOUND SCROLL TO THE BOTTOM AND CLICK ON THE GREEN BAR
- 5. SIGN OFF ON ASSET INPECTION BY CLICKING YES

04 <b>월 강</b> G 가 X Ni <b>9</b> 약 세 30% &	8:05 ■ a G an X NI © % al 30% &
Asset Inspection X	C Asset inspection
Vehicle	JUNESTI
JCTtest1 Dec 6, 2023 12:27 PM Previous report certified	Previous inspection Reviewed 🗸
Loaded truck	This vehicle was inspected in accordance with regional and/or federal regulations.
li Inspect	Expand previous inspection
	Default Trailer Defects List
	Default Vehicle Defects List
	Default Vehicle Defects List
	Default Venicle Defects List
	Required checklist
	✓ Load Height - Format (ft.in) No defects* □
	Load Height - Format (ft.in) MAJOR
	Other Add Defect
	Other parts (optional)
Skip remainder	Autohauler Defects
III O <	III D <
III □ < S = E G # X N N O S. d. 39% & Asset Inspection test driver 1 ©	III O K 20 C Corr X NO C ASSA Asset Inspection Corr Corr Corr Corr Corr Corr Corr Corr
III □ < a @ ■ or # X *19 *0 al ans # + Asset Inspection	III O ≺ B20 ■ Core X NO * #10 * # data Asset Inspection → Hyperatics → Lights and Reflectors
III □ < Set of end of a set of the set of	III C < R20 ■ Boxe X NI © % 4 30% 4 A Set Inspection → Hydramics → Lights and Reflectors → Mirrors
III □ < Source Source	III C <
III C C Second Control of Advances of the second control of the s	III C <
III     Image: Control State	III D < E20 ■ B or ★ X ★I 9 % # 30% # A Asset Inspection ← tytestrics → Lights and Reflectors → Mirrors → Steering → Tires
III C    Control And Adaptation And	III C <  E20 = Box + X NIP 7, 430(4)  E20 = Box + X NIP 7, 430(4)  Accel Inspection  Cyclosence  Lights and Reflectors  Mirrors  Siteering  Trice  Sign Asset Inspection
III □ < Asset Inspection ▲ test driver ▲ 1 ● Vour ELD has diagnostics. Tips for details Lights and Reflectors Steering Tires Wheels and Rims Windshield Wipers	III C < R20 € BG + X N 0 * 4 3244 < Asst Inspection > Lights and Reflectors > Lights and Reflectors > Steering > Tires Sign Asset Inspection This vehicle was inspected in accordance with regional and/or federal regulations
III C C C C C C C C C C C C C C C C C C	III     ✓       \$200 = Bits = X     NIO Total 30x8
III     Image: Control of the state of the s	III        EXX #10 * 430x4       * Asset Inspection       * How Asset       * Lights and Reflectors       > Mirrors       > Steering       > Tres       Sign Asset Inspection       This vehicle was inspected in accordance with regional and/or federal regulations       No     Yes       0201 N 131st St, Omaha, N     08164, USA
III C C C C C C C C C C C C C C C C C C	III          100       State inspection         111       State inspection         112       State inspection         113       State inspected in accordance with regional and/or federal regulations         No       Yes         0201 N 131st St, Omaha, N.       08164, USA         Save New Inspection
III     IIII     IIII     IIII     IIII     IIIIII     IIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII	III          R20 = ■ or # X       N = * A 30x 4         * Assel Inspection       * If 0 = * A 30x 4         * Lights and Reflectors       * Mirrors         > Siteering       * Trees         Sign Asset Inspection       This vehicle was inspected in accordance with regional and/or federal regulations         No       Yes         6201 N 131st St, Omaha, N       B8164, USA         Save New Inspection       TRUCK PARKED IN LANSING LOT B SPOT 18
III     <	III C ✓
III C C MANAGER OF MANOR OF MA	III C C

#### STEP 4 – DEFECTS FOUND ON THE INSPECTION

- 1. CHOOSE THE CATEGORY OF THE DEFECT AND CHOOSE ADD DEFECT
- 2. A COMMENT BOX WILL APPEAR PLACE AS MUCH DETAIL OF THE DEFECT AS POSSIBLE IN THE BOX

de Gar)

Asset Inspection
 Autohauler Defects
 Brakes (Parking)
 Brakes (Service)

Dragging

Leaking air

Cleaking fluid

Seized

Warning light not working

III O

Warning light on

Air compressor not working

Chatters, shudders, or vibrates

AIR LEAKING FROM RIGHT REAR AXEL

NI O 10 1 34%

1 defect

Add Defect

Add Defect

Add Defect

Remo

Add Defect

Add Defect

Add Defect

Add Defect

3. A CAMERA WILL ALSO APPEAR, TAE A PICTURE OF THE DEFECT. WHEN YOU CHOOSE THE CAMERA. YOU CAN EITHER TAKE A PICTURE OR UPLOAD ONE.

ABEGTX Asset Inspection	<b>*1 ♥</b> % µ1 33% &
Autohauler Defects	
<ul> <li>Brakes (Parking)</li> </ul>	
<ul> <li>Brakes (Service)</li> </ul>	
Air compressor not prking	Add Defect
Chatters, shudders, or vibrates	Add Defect
Dragging	Add Defect
Leaking air	Add Defect
Leaking fluid	Add Defect
Overheating or running hot	Add Defect
Seized	Add Defect
Warning light not working	Add Defect
Warning light on	Add Defect
Weak or ineffective	Add Defect
Other	Add Defect
III 0	<

IN THE CASE SHOWN, A BRAKE DEFECT WAS FOUND. AIR WAS FOUND LEAKING FROM THE RIGHT REAR TRACTOR AXLE. BE SURE TO MAKE THE APROPRIATE COMMENTS WITH DETAIL. ALSO, ADD A PICTURE FOR EVEN MORE DETAIL. THIS WILL HELP THE MECHANIC SAVE TIME AND EASILY FIND THE DEFECT.

8:18 <b>4 6 6 * X</b>	<b>NI O</b> % a) 34% &
Autohauler Defects	
<ul> <li>Brakes (Parking)</li> </ul>	
<ul> <li>Brakes (Service)</li> </ul>	
Air compressor not working	
Chatters, shudders, or vibrates	Add Defect
Adding Image	×
Please choose an option to add a	n image.
New picture Uploa	ad
Leaking fluid	
Overheating or running hot Seized Warning light not working	
Overheating or running hot Seized Warning light not working Warning light on	

**STEP 5– FINISHING OUT THE INSPECTION** 

- 1. SCROLL TO THE BOTTOM. IN THE COMMENT SECTION, PLACE THE LOT AND LOCATION OF YOUR TRUCK. BE SPECIFIC! THIS WILL EASILY HELP THE SHOP LOCATE YOUR TRUCK
- 2. SIGN THE ASSET INSPECTION
- 3. ONCE THE INSPECTION IS COMPLETE PHYSICALLY NOTIFY YOUR SHOP THAT REPAIRS ARE REQUIRED. DO NOT ASSUME THAT THE ELETRONIC TRANSMISSION WAS SENT. VERIFY YOUR SHOP IS AWARE OF THE REPAIRS REQUIRED.

NI O 😤 // 35% &

19 🗃 🖬 G 🛱	×				<b>41 0</b> % at 35%	: <b>a</b>	8.20 a a a G # X	NI 0 1
<ul> <li>Asse</li> </ul>	t Inspectio	on					← Asset Inspection	
Winds	hield Wipe	ers					7 Tryunations	
							Lights and Reflector	
Inspectio	n locatio	n			ø			
6201 N 13	R1st St On	naha NE 6/	8164 USA	Δ			Mirrors	
02011110	, 01	10110, 112 00	,00				Steering	
Save Nev	v Inspect	ion					Tires	
TRUCK P	PARKED IN	LANSING	LOT B SP	OT 18			Sign Asset Inspectio	00
							oigh Asset hispeetic	
		🛛 Don	ie				This vehicle was inspec	te in accordance with regi
							and/or federal regulatio	<u>n:</u>
25							No	Yes
(9)		18	8				6201 N 131st St. Omah.	1 68164. USA
1 2	3 4	5 6	7 8	9	0 Del			
q w	e r	t y	u i	0	p 🛛			
	0 1	3 3	6 *	. (	)		Save New Inspection	
a s	s d	t g	hj	K	Go		TRUCK PARKED IN LAN	ISING LOT B SPOT 18
+ z	x c	v b	n n	n , L	.? +			
Ctrl 1#1		English (I	US)		d D			
		0						
		0	_	~				0 <

#### STEP 6 - CERTIFYING THE REPAIRS

- 1. ON THE DASHBOARD, THE INSPECTION ICON WILL BE MARKED IN RED. CLICK ON IT
- 2. THE VEHICLE INFORMATION WILL APPEAR WITH THE WORD REPAIR IN THE RED BAR.
- 3. SCROLL TO THE AREA OF THE DEFECT AND ADD AS MUCH INFORMATION AS POSSIBLE



3:23 🗃 🛅 Ġ 🕶 🗲				NI 9 % al 369
Asset Inspe	ection	<u>.</u>		🌲 2 👒
	Your ELD	has diagnostics. Tap	for details.	
Dehicle	9			
Dec 7, 2023 7	:21 AM		🗲 Unreso	lved defects
<b>TRUCK</b>	PARKED	IN LANSING LO	T B SPOT	18
		🖋 Repair		
Dashboard	Č	Asset Inspection	Messages	More

CHECK THE BOX REPAIRED, PLACE THE REPAIR ORDER NUMBER, REPAIRING SHOP, MECHANICS NAME, IN THE BOX



#### STEP 6 - CERTIFYING THE REPAIRS

- 1. MAKE SURE ALL BOXES FOR REPAIRED ITEMS ARE CHECKED REPAIRED
- 2. SCROLL TO THE BOTTOM AND CLICK SAVE
- 3. CERTIFY THE REPAIRS
- 4. YOU CAN NOW REPEAT THE PROCESS OF PRE-TRIPPING THE TRUCK

Asset Inspection 📃 test drive	er 🛕 2 🎅	8:35 🖝 🔤 🖂 🕫	×		NI 0 %	al 40% &
Your ELD has diagnostics. Tap for details		🔶 Asse				
<ul> <li>Load Height - Format (ft.in)</li> </ul>	2 defects					
Load Height - Format (fLin) MAJOR	- ACCOUNT OF A COUNT OF	<ul> <li>Lights</li> </ul>				
₽ 13.6		Mirror				
Not repaired     Repaired or not a defect		 • Steen				
		> Tires	6			
Repair not necessary for the safe operation	n of the vehicle	Sign As	set Inspectio	on		
HEIGHT AND CLE RANCES NO	W GOOD	284 28700 - 289				
Other		This vehi and/or fe	ederal regula	ted in accordanc	e with reaio	nal
E TIGHT LOAD			No		Yes	
Not repaired     Provide a pot a defeat		6201 N 1	31st St, Oma	, NE 68164, USA		
Repaired or not a delect						
Repair not necessary for the safe operation	n of the vehicle					
13.6						
🗡 Save						
III 0 <			III	0	<	
		200				

